

OFF/SUB DIVISIONAL ENGINEER PWD(B & R PUNHANA)

OFFICE ORDER NO. .

DATED-


BUILDING SAFETY CERTIFICATE

CERTIFIED THAT THE SCHOOL BUILDING OF G.M.S.S.S SCHOOL SAROLI WAS INSPECTED BY SHRI NASEEM AHMED J.E WITH UNDERSIGNED

THE DETAIL OF ROOMS AS UNDER

1. ROOM NO. 1 TO 7 REQUIRED RAISING AND NOT FIT TILL REPAIR
2. ROOM NO. 8 TO 13 WITH VARANDAH ARE NOT FIT FOR HUMAN USE
3. ROOM NO. 20 and 21 SLAB DAMAGED AND NOT FIT TILL REPAIR
4. ROOM NO. 14 TO 19 AND 22 TO 44 TOTAL 29 ROOMS (CLASS ROOMS, LAB, LIBRARY etc.) ARE IN GOOD CONDITION AND FIT FOR HUMAN USE .
OFFICE AND STAFF ROOM ARE ALSO IN GOOD CONDITION.

*Naseem Ahmed
JE PWD*


Sub Divisional Engineer
Provincial Sub Division
PWD B & R Punhana