

OFF/SUB DIVISIONAL ENGINEER PWD(B & R PUNHANA)

OFFICE ORDER NO. *sp1/157*

DATED- *18-05-23*

BUILDING SAFETY CERTIFICATE

CERTIFIED THAT THE SCHOOL BUILDING OF G.M.S.S.S SCHOOL SAROLI WAS INSPECTED BY SHRI NASEEM AHMED J.E WITH UNDERSIGNED

THE DETAIL OF ROOMS AS UNDER

- 1. ROOM NO. 1 TO 7 REQUIRED RAISING AND NOT FIT TILL REPAIR**
- 2. ROOM NO. 8 TO 13 WITH VARANDAH ARE NOT FIT FOR HUMAN USE**
- 3. ROOM NO. 20 and 21 SLAB DAMAGED AND NOT FIT TILL REPAIR**
- 4. ROOM NO. 14 TO 19 AND 22 TO 44 TOTAL 29 ROOMS (CLASS ROOMS, LAB, LIBRARY etc.) ARE IN GOOD CONDITION AND ^{seems} FIT FOR HUMAN USE . OFFICE AND STAFF ROOM ARE ALSO IN GOOD CONDITION.**

sh
J E Pwd

sh
Sub Divisional Engineer
Provincial Sub Division
PWD B & R Punhana